




STEP 1

On a clean, flat surface, lay tabletop ① upside down











STEP 2

Using the provided hex wrench **F** secure leg assemblies (2) to the tabletop using the large washers (2) and the 30mm bolts (3). Repeat step 2 for remaining leg assembly.



STEP 3

Using the provided Allen wrench @secure stretcher ③ to leg assemblies using the small washers @ and the 21mm bolts **D**.



STEP 4

Using the provided Allen wrench **(c)** secure the V-Brace (4) using the small washers **(C)** and the 21mm bolts **(D)** as shown. Lastly, use the 64mm bolts **(E)** to secure V-Brace to stretcher as shown.

